DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-018145 Address: 333 Burma Road **Date Inspected:** 10-Nov-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Yang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A Weld Procedures Followed: N/A **Electrode to specification:** No Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS: Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component: OBG** Segments

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dan Hernandez was present during the times noted above to observe the fit up, welding and related activities associated with the fabrication of the San Francisco Oakland Bay Self Anchored Suspension Bridge at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

OBG Trial Assembly Yard

Segment 11DW/11EW

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated OBW11C-007, Side Plate transverse splice. The welder is identified as #046709 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated OBW11C-009, Side Plate transverse splice. The welder is identified as #040656 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated DP682-001-020, Deck Plate I-rib splice. The welder is identified as

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

#040611 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-3213-B-U3b.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated DP695-001-020, Deck Plate I-rib splice. The welder is identified as #044551 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-3213-B-U3b.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated EP144-001-032, Edge Plate I-rib splice. The welder is identified as #057333 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated OBW11A-009, Deck Plate transverse splice. The welder is identified as #057333 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

Segment 11CE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a fillet weld joint. The Weld joint is designated SP637-001-035, Side Plate WT stiffener hold back weld. The welder is identified as #040367 and was observed welding in the 2F (horizontal) position using approved Welding Procedure Specification WPS-B-T-2132.

Segment 11DE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a fillet weld joint. The Weld joint is designated SP638-001-016, Side Plate WT stiffener hold back weld. The welder is identified as #040367 and was observed welding in the 2F (horizontal) position using approved Welding Procedure Specification WPS-B-T-2132.

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated SEG072C-043, Longitudinal Diaphragm web to Floor Beam. The welder is identified as #047353 and was observed welding in the 3G (vertical) position using approved Welding Procedure Specification WPS-B-T-2233-TC-U4b-F.

Segment 11CE/11DE

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated EP158-001-013, Edge Plate I-rib splice. The welder is identified as #040320 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated SP702-001-034, Side Plate I-rib splice. The welder is identified as #067752 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

Segment 11DE/11EE

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated OBE11A-006, Edge Plate transverse splice. The welder is identified as #053871 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-B-U2-FCM-1.

Segment 11EW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Partial Joint Penetration (PJP) weld joint. The Weld joint is designated LB3-004-058, Light Bracket to Deck Plate. The welder is identified as #040609 and was observed welding in the 2G (horizontal) position using approved Welding Procedure Specification WPS-B-T-2232-TC-P4-F-1.

Segment 11DE

ZPMC personnel began using the ESAB E71T-1M Dual Shield 70 Ultra Plus electrode in production welding in the OBG Trial Assembly. Welding was performed in Segment 11DE at panel point 104 (cross beam side). The components welded were the Longitudinal Diaphragm web to Floor Beam. The weld joint is a Complete Joint Penetration, single bevel T-Joint without backing in the 3G (vertical) position. Root pass is to be Carbon Air Arc back gouged. The approved Welding Procedure Specification used was WPS-B-T-2233-ESAB. The approved welder was identified as #047353. The weld joint is identified as SEG072B-043.

For the above mentioned welding activities ZPMC Quality Control (QC) Inspectors are identified as An Qing Xiang, Shi Lei and Zhou Peng. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Segment 11CW/11DW

This QA Inspector observed ABF personnel performing Ultrasonic Testing on the Side Plate transverse CJP splice, cross beam and counter weight side. D scan was performed.

Segment 11DE/11EE

This QA Inspector observed the removal of fit up plate form the Side Plate transverse Splice by arc gouging, cross beam side.

Segment 11CE

This QA Inspector observed drilling of bolt holes in the Edge Plate for Suspender Bracket connection at panel

WELDING INSPECTION REPORT

(Continued Page 4 of 4)

point 102.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
Reviewed By:	Dsouza, Christopher	QA Reviewer